



PM118B True RMS

2000V DMM WITH CLAMP-ON ACA/DCA

- 6,000 counts LCD display with backlit
- **Upto 2000V AC/DC** for **solar system** measurement
- Non-contact AC voltage (NCV) and live wire test
- **VFD** (Variable-frequency Drive) measurement
- **True RMS, AC+DC** voltage measurement
- Data hold, Min /Max /Relative measurement
- Clamp AC/DC current measurement (optional)
- Torch lamp, auto ranging, auto power-off
- Safety as per IEC1010-1 Cat.III 1500V

Technical specifications

DCV: 600m/6/60/600/1000/2000V, $\pm 0.5 \sim 0.8\%$

ACV: 600m/6/60/600/1000/2000V, $\pm 0.8 \sim 1.5\%$

DCA: 600 μ /6m/60m/600m/10A, $\pm 0.8\%$

ACA: 600 μ /6m/60m/600m/10A, $\pm 1.0\%$

Clamp DCA/ACA: 60A(10mV/A)/600A(1mV/A), $\pm 0.5\%$

OHM: 600/6k/60k/600k/6M/60M Ω , $\pm 1.0\%$

CAP: 60n/600n/6 μ /60 μ /600 μ /6m/100mF, $\pm 4.0\%$

TEMP: $-40^{\circ}\text{C} \sim 1000^{\circ}\text{C}$, $-40^{\circ}\text{F} \sim 1832^{\circ}\text{F}$, $\pm 1.0\%$

FREQ: 10/100/1k/10k/100k/1M/10MHz, $\pm 0.5\%$

Duty cycle: 1%~99%, $\pm 3.0\%$

Audible continuity and diode test

Battery: 1.5Vx3, AAA size

Dimensions & weight: 194x90x56mm, 380g approx.

Optional clamp: PM3300 or PM3301

PEAKMETER®

by Sinometer

www.peak-meter.cn

Email: sales@peak-meter.cn