



## PM18A True RMS

### WORKSHOP DMM WITH TORCH LAMP

- 6,000 counts LCD display with backlit
- Non-Contact AC voltage detection in 3 levels
- Audible continuity test in 3 levels
- **Extra bright torch lamp** built on back
- True RMS AC measurement (40Hz~1kHz)
- Display frequency at ACV /ACA measurement
- Data hold, auto ranging, auto power-off
- 10A/1000V fused, full ranges protection
- Safety: Cat.III 1000V and Cat. IV 600V

#### Technical specifications

DCV: 600m/6/60/600/1000V,  $\pm 0.5\%$

ACV: 6/60/600/750V,  $\pm 0.8\%$

DCA: 60 $\mu$ /600 $\mu$ /6m/60m/600m/10A,  $\pm 0.8\%$

ACA: 60 $\mu$ /600 $\mu$ /6m/60m/600m/10A,  $\pm 1.0\%$

OHM: 600/6k/60k/600k/6M/60M  $\Omega$ ,  $\pm 0.8\%$

CAP: 6n/60n/600n/6 $\mu$ /60 $\mu$ /600 $\mu$ /6m/100mF,  $\pm 4.0\%$

TEMP: -20 $^{\circ}$ C~1000 $^{\circ}$ C, -4 $^{\circ}$ F~1832 $^{\circ}$ F,  $\pm 1.0\%$

FREQ: 10/100/1k/10k/100k/1M/10MHz,  $\pm 1.0\%$

Duty cycle: 5%~95%,  $\pm 2.0\%$

Continuity: <40  $\Omega$ , 40  $\Omega$ ~60  $\Omega$ , >60  $\Omega$

Diode test: 1mA/3.2V

Dimensions & weight: 190x89x50mm, 360g approx.

Battery: 1.5Vx4, AA size

Accessories: holster, temp probe

**PEAKMETER**<sup>®</sup>

by Sinometer

[www.peak-meter.cn](http://www.peak-meter.cn)

Email: [sales@peak-meter.cn](mailto:sales@peak-meter.cn)